



**MACQUEEN™**

MacQueen  
4607 SE Rio Court  
Ankeny, IA 50021  
515-289-9994 • 800-933-1190

Ship To: SAME AS BELOW

Invoice To: CITY OF BLOOMFIELD  
111 W Franklin  
Bloomfield IA 52537

Branch 03 - ANKENY IA		
Date 07/17/2024	Time 10:59:42 (O)	Page 1
Account No BLOOM002	Phone No 6416642260	Est No 01 003262
Ship Via	Purchase Order NEED	
Tax ID No		
	Salesperson 444	

ESTIMATE EXPIRY DATE: 08/16/2024

**SERVICE ESTIMATE - NOT AN INVOICE**

\*\*\*\*\* Segment 01 \*\*\*\*\*

Stock #: C047284 ROVVERX MS #: 5604427  
Make: EN Model: RX130  
Is to have the following work done

PM SERVICE

CAUSE:

7/16/24. 95456. HOOKED UP CRALWER TO STUDIO. RAN THROUGH ALL FUNCTIONS. ALL FUNTIONS ARE WORKING CORRECTLY. SUGGEST DOING PM SEAL KIT TO REPLACE ALL O RING. HAVE TO REPLACE TWO CONNECTORS DUE TO DISSASMBLING OF CRALWER. SUGGESTED REPLACING REAR WINDOWS DURNING PM. SOFT WARE NEEDS UPDATED FROM 8.31.0 TO MOST CURRENT. CURRENT SOFTWARE IS AT 8.52.0

ADDITIONAL DESCRIPTION:

CUSTOMER REQUEST A PM SERVICE QUOTE WITH SYSTEM UPDATE.

<u>Part#</u>	<u>Description</u>	<u>Qty</u>	<u>Price</u>	<u>Amount</u>
E-560-9320-00-SP	Seal Kit RX130	1	269.32	269.32
E-371-0332-00	GREEN PIN 6	1	12.71	12.71
E-371-0326-00	WHITE PIN 4	1	5.73	5.73
E-560-0033-00	REAR WINDOW	2	27.96	55.92

Parts: 343.68  
Labor: 2430.00  
Subtotal: 2773.68

Authorization: \_\_\_\_\_

\*\*\*\*\* Segment 02 \*\*\*\*\*

VC500 UPDATE

ADDITIONAL DESCRIPTION:

CUSTOMER REQUESTS QUOTE FOR VC500 TO BE UPDATED.



**MACQUEEN™**

**Ship To:** SAME AS BELOW

**Invoice To:** CITY OF BLOOMFIELD  
111 W Franklin  
Bloomfield IA 52537

MacQueen  
4607 SE Rio Court  
Ankeny, IA 50021  
515-289-9994 • 800-933-1190

Branch 03 - ANKENY IA		
Date 07/17/2024	Time 10:59:42 (O)	Page 2
Account No BLOOM002	Phone No 6416642260	Est No 01 003262
Ship Via	Purchase Order NEED	
Tax ID No		
	Salesperson 444	

ESTIMATE EXPIRY DATE: 08/16/2024

**SERVICE ESTIMATE - NOT AN INVOICE**

Authorization: \_\_\_\_\_

Labor:	101.25
Subtotal:	101.25
Parts:	343.68
Labor:	2531.25
TOTAL:	2874.93