



**MACQUEEN™**

MacQueen  
4607 SE Rio Court  
Ankeny, IA 50021  
515-289-9994 • 800-933-1190

**Ship To:** SAME AS BELOW

**Invoice To:** CITY OF BLOOMFIELD  
111 W Franklin  
Bloomfield IA 52537

Branch 03 - ANKENY IA		
Date 07/17/2024	Time 11:00:21 (O)	Page 1
Account No BLOOM002	Phone No 6416642260	Est No 01 003263
Ship Via	Purchase Order NEED	
Tax ID No		
	Salesperson 444	

ESTIMATE EXPIRY DATE: 08/16/2024

**SERVICE ESTIMATE - NOT AN INVOICE**

Stock #: C047283 CAMERA MS #: 5614452  
Make: EN Model: RCX90  
Is to have the following work done

LEAK

CAUSE:

7/16/24. 95456. HOOKED CAMERA UP TO STUDIO AND TESTED  
FUNCTIONS OF CAMERA. CAN PANS AND TILTS WITH NO ISSUES.  
LIGHTS AND LAZERS WORK CORRECTLY. PRESSURIZED CAMERA TO  
CHECK FROM LEAK. FOUND SMALL LEAKS AROUND FRONT LENS IN  
COUPLE DIFFERENT SPOTS. FRONT HOUSING HAS BEEN DAMAGED AROUND  
THE EDGES OF THE LENS. SUGGEST REPLACING FRONT CAMERA  
HOUSING. SUGGEST PM SEAL KIT FOR CAMERA AND CLEANING.  
SOFTWARE IS AT 8.31.0. NEEDS TO BE UPDATED TO MOST CURRENT  
WHICH IS 8.51.0

ADDITIONAL DESCRIPTION:

CUSTOMER STATES UNIT WILL NOT HOLD PRESSURE AND HAS A  
CRACKED LENSE.  
CHECK AND QUOTE. INCLUDE A PM SERVICE IN THE QUOTE.

<u>Part#</u>	<u>Description</u>	<u>Qty</u>	<u>Price</u>	<u>Amount</u>
E-561-9320-00-SP	RCX90 PM KIT	1	161.34	161.34
E-561-0120-04-SP	FNT LED LIGHT	1	1691.20	1691.20
			Parts:	1852.54
			Labor:	1417.50
Authorization: _____			TOTAL:	3270.04